Tele:

200**@//20**3/E2

Garrison Engineer St Thomas Mount Chennai-16

o6 Jan 2022

Kendriya Vidyalaya DGQA Palavanthangal Chennai

## REQUEST TO ISSUE STRUCTURAL SAFETY CERTIFICATE FOR THE SCHOOL BUILDING OF KV DGQA

- Ref Your letter No F.School Building/KVDGQA/2021-22 dt 08 Dec 2021.
- 2. On visual Inspection, it is opined that the Kendrya Vidyalaya buildings at Palavanthangal have been found structurally safe. However, the following are suggested to enhance the life of buildings
  - (a) Vegitation/small shurbs found on the roof and wall surfaces at certain location of the buildings to be removed regularly.
  - (b) Structural safety of the building to be checked yearly to observe, if any changes found during the year.
- This is for your info and necessary action please.

Mally (B Bhushana Reddy) AE (Civil) Offg GE STM

Kenewal after one year